

# Quality Testing Laboratory



## Thickness tester



Thickness tester is used to measure the thickness of poly film in Microns.

## Universal Tensile tester



Universal tensile tester is used to measure Tensile properties like Tensile strength, Elongation, Seal strength, Coefficient of Friction, Loop tack test and Tear test.

## Opacity tester



Opacity tester is used to measure Optical properties like Transperency and opacity of poly film.

## Falling Dart impact machine



Falling dart impact machine is used to measure dart failure value of poly film in Grams

## Scuff resistance tester



Scuff resistance tester is used to measure ink adhesion strength on printed poly film.